


FIG. 1



# FIG. 2




FIG. 3







FIG. 4



# F I G . 5


$L^* = 90$





# F I G . 7


$L^* = 80$



000001 6/6/60


# F I G . 8

$L^*=75$



# F I G . 9


$L^* = 70$






# F I G . 10


$L^* = 65$



$$L^* = 60$$


# F I G . 12


$L^* = 55$



009021 6/6/8/60

# F I G . 13


$L^* = 50$



008021" E/67E/50


# F I G . 14

$L^* = 45$



# F I G . 15


$L^* = 40$



000001" E6TE60

# F I G . 16


$L^* = 35$



008027 " 6/6FE/60

# F I G . 17

$L^* = 30$




000021 6/61E/60



F I G . 18


$L^* = 25$



003027 0.267E+00


F I G . 19

$L^* = 20$




F I G . 20

$L^* = 15$




# F I G . 21

$L^*=10$




F I G . 22

$L^* = 5$



# F I G . 23A



# F I G . 23B

R	G	R	G
G	R	G	R
B	G	B	G
G	B	G	B
R	G	R	G
G	R	G	R

# F I G . 23C

Ye	Cy	Ye	Cy
Mg	G	Mg	G
Cy	Ye	Cy	Ye
Mg	G	Mg	G
Ye	Cy	Ye	Cy
Mg	G	Mg	G
Cy	Ye	Cy	Ye
Mg	G	Mg	G

# F I G . 23D

	R	G	B	
G		B	R	G
	R	G	B	
G		B	R	G
	R	G	B	